



Canon CLI-8, CLI-221, CLI-226 & PGI-5, PGI-220, PGI-225 Chip Replacement Instructions



A dab of hot glue or instant glue may be needed to hold the chip in place. When using glue, be sure not to cover any contacts with it.